

PERSONAL PROTECTIVE EQUIPMENT (PPE) STANDARDS *For Drivers*

**Hard
Hat**

**Safety
Glasses**
ANSI Z87.1 Rated

**H2S
Monitor**

At facilities
where Hydrogen
Sulfide products
are present

REQUIRED AREAS

- Loading and Unloading Racks (Refined Product and Crude Oil)
- Includes Butane, Natural Gasoline, Ethanol and Additives



**FIRE RESISTANT
CLOTHING MUST
BE WORN AS THE
OUTER LAYER IN
ALL WEATHER
CONDITIONS**

**Flame
Resistance
Clothing
(FRC)**
Lab coat at a
minimum

**Leather
Gloves**

When connecting
and
disconnecting
loading arms

**Leather
Boots**

Closed-toed
boots with
slip-resistant
soles

EQUIPO DE PROTECCIÓN PERSONAL (PPE) ESTÁNDARES *Conductores*

Casco

Gafas de seguridad

ANSI Z87.1 con puntuación

Monitor de H₂S

En instalaciones donde están presentes productos de ácido sulfhídrico

ÁREA REQUERIDA

- Carga y extracoronario (Producto refinado y aceite crudo)
- Incluye butano, gasolina natural, diálisis y aditivos



LA ROPA RESISTENTE AL FUEGO DEBE USARSE COMO LA CAPA EXTERIOR EN TODAS LAS CONDICIONES CLIMÁTICAS

Ropa resistente a las llamas (FRC)

Capa para análisis de laboratorio como mínimo



Guantes de cuero

Al conectar y desconectar los brazos de carga

Botas de cuero

Cerradas, con suelas antiderrapantes.

POR FAVOR, DIRIJA CUALQUIER PREGUNTA A SU CENTRO TERMINAL