

PERSONAL PROTECTIVE EQUIPMENT (PPE) STANDARDS *For Drivers*

WHAT'S THE SAME

- **Safety Eyewear**—ANSI Z87.1 approved with side protection.
- **Leather Boots**—closed-toed boots with slip-resistant sole.
- **Gloves**—leather or similar to be worn when connecting and disconnecting the load arms.

**At Facilities that load/unload products that may contain hydrogen sulfide (H₂S) you must also wear:

- **H₂S Monitor**—worn on your person.



WHAT'S NEW

- **Hard Hat**
- **Flame Resistant Clothing (FRC)**
 - *Long-sleeved shirt and long pants
 - *FR Lab Coat at a minimum with long pants

Effective Date
May 1, 2024



REQUIRED AREAS

- **Loading and Unloading Racks (Refined Product and Crude Oil)**
- **Includes Butane, Natural Gasoline, Ethanol and Additives**



PLEASE DIRECT ANY QUESTIONS TO YOUR TERMINAL FACILITY